

# ACTIVE - P

A phosphoric based, acidic compound for the removal of rust, scale and light oils, providing a light phosphate coating prior to painting.

## Dilutions

Use at 5 - 500 ml / L (1:200 - 1:2) dilution with water depending on application. Use at ambient to 70 °C until surface is clean. Always use gloves and protective clothing when handling or decanting this product.

## GHS Identification:

Danger

**UN1805 – Phosphoric Acid Solution**



## PPE

Gloves, Goggles, Personal Protective Clothing, Gumboots



First Aid

SKIN	EYES	INHALATION	ORAL
Remove/take off all contaminated clothing immediately. Rinse skin with water.	If in EYES rinse cautiously with water for several minutes, remove contact lenses if safe and easy to do. Continue rinsing, seek medical help.	If INHALED and breathing is difficult – remove person to fresh air and seek medical attention	Do NOT induce vomiting
If skin irritation persists consult a doctor.			Consult a Doctor immediately
			Drink Water / Milk , Egg Whites
			Consult a doctor immediately.

## Available in

Drums - 5Lt, 25Lt